

POSTED
at 11h30m

Stewards
Log N° 80

From The Technical Delegate
To The Stewards of the Meeting

Report N° 06

After the race we have checked cars 58, 50, 3, 11, 78, 52, 888 and 87 on:

1. Weight
2. Ride Height
3. Aero devices
4. Restrictor and intake measurement
5. Engine settings
6. Anti-roll bars
7. Boost on Turbo cars
8. Extra lights article 118

After the final checks all cars, excepted car 888 are complying with their current homologation files, technical regulations, tyre lists and the bop decisions.

Car 888 didn't comply with art 14.2 of art 257 A from appendix J : Elastic cords attached to the shoulder straps are forbidden. Car 888 had elastic cord attached on the right hand side shoulder strap. The car is still in parc fermé condition in the Race Center.

*SRO BLANCPAIN
C. SURMONT.*

Claude Surmont

Technical Director SRO
Technical Delegate for this event
Lic RACB n°2774

Date 26 June 2016

Time 10:30

Document

Copy to: The Race Director

The Clerk of the Course

The Secretary of the Meeting