

POSTED at
31/05/2026, 13:17:03

BULLETIN No. 05

From: The Stewards	Date: 31 May 2026
To: All Competitors All Officials	Time: 13:15 hrs
	Number of Pages: 1

The Stewards notify those concerned of the following:

Fuel Sensor Failure - Minimum Pit Stop Time - Amendment

In accordance with Article 502.13 b) of the GT Challenge Europe Sporting Regulations, the Stewards advise that the minimum pit stop time for any refuelling pit stop (except for 'short' refuelling stops) with no refuelling data is **81 seconds**.

All stops with no refuelling data will be checked using the pit gantry camera footage.

Luis ROBY
Steward (Chair)

Yves BACQUELAINE
International Steward

Wim COOLS
International Steward


Paolo LONGONI
ASN Steward



Luis Roby
Chair-Steward
PT26-0509
31/05/2026, 13:16:25



Yves Bacquelaîne
Steward
RACB 001
31/05/2026, 13:16:25



Wim Cools
Steward
RACB 3841
31/05/2026, 13:16:26



Paolo Longoni
Steward
ACI47736
31/05/2026, 13:16:26

