



From

The Stewards of the Meeting

Decision N° 68

Antonelli Motorsport - cars nr 38

The Stewards, having received a technical report, take the following decision.

Car/Driver

38

Competitor

Antonelli Motorsport

Facts

The engine has been changed

Offence

Breach of Art. 152 of the BGTS Sporting Regulations

Penalty

Start the race from the pit lane

The competitor was granted a hearing before the decision. He is reminded of his right of appeal.

Yves BACQUELAINE International Steward Chairman

Marc JANSSEN
International Steward
Permanent Chairman BGTS

Richard NORBURY International Steward

Greg WASTERS
International Steward

Alessandro TIBILETTI International Steward

09.40

Mathieu REMMERIE ASN Steward

Date

30 July 2016

Time

Stewards Log N°. 123

Received by the Competitor >

(Signature)

Date 30.7.16

Time ... 950

Copy to: The Competitor

The Clerk of the Course
The Secretary of the Meeting

The Press Delegate
The Timekeepers

The Official Notice Board







From

The Technical Delegate

Report Nº 11

To

The Stewards of the Meeting

Stewards Log N° 1.23

Car n° 38 from Team ANTONELLI (Lamborghini Huracan GT3) had his engine changed.

The new engine has been sealed by us.

Alain Marquet (RACB Lic 2265)

Series Technical Delegate

Date 30 July 2016

Time

9:00

Marquel









































Antone Motor Sport

Stewards Log Nº 123/A

EVENT:

24h SPA

DATE:

30 July 2016

TEAM:

Antonelli Motorsport

CAR:

Lamborghini

Number:

#38

Subject:

Engine Change

TO:

Stewards of the Meeting

Due an Engine failure in the night Qualifying (23:50 causing FCY) we were forced to change the engine in the car. After confirming with the technical delegates we changed the engine.

New Engine is sealed by the Scrutineers and changed in the SRO Passport!

We kindly ask to get permission to start at the end of the Grid the race

Signature Marco Antonelli
Date 30.07.2016

Sent to Stewards

09-27

I propose to get them to sport from the pit boul.

A.C.	Checks List Name of the event: 24 heures de Spa Date: 25 30 failler					№ 38	
	Characteristics Declared					Checked	
Restrictors	ØA 38 N°, Ø			37.86		615 Rostrick	200
	ØВ	38 N°,	S. (C. S.	242	6	04 7 23/180	je
Car Weight	Minimum, Empty weight			BOP ballast		-3 680 -2 681	>
	Ballast	Yes No	kg	j		-0445 March	
Height of the chassis	Front	mm 65,5	5			And the second second	
from the ground	Rear	mm 128	12/01/01				
	Technical Remarks					Action	
,		152.8	153.				
			Si	gnatures			
Date :	Competitor				Mail Mail	in MARQUET vissaire Technique Lic. 2265	



Stewards Log N°. 123.10

EVENT:

24h SPA

DATE:

30 July 2016

TEAM:

Antonelli Motorsport

CAR:

Lamborghini

Number:

#38

Subject:

Engine Change

TO:

Stewards of the Meeting

Due an Engine failure in the night Qualifying (23:50 causing FCY) we were forced to change the engine in the car. After confirming with the technical delegates we changed the engine.

I propose to get them to Start from the fort lane

New Engine is sealed by the Scrutineers and changed in the SRO Passport!

We kindly ask to get permission to start at the end of the Grid the race

Signature Marco Antonelli

Date

30.07.2016

Alain ADAM Race Director

RACB 1632

Sent to Stewards

at

09.17