

STEWARDS
LOG NR 119

POSTED
at 16:10

DECISION No.: 38

- Bronze Test
- Free Practice 1
- Free Practice 2
- Qualifying
- Qualifying Race
- Main Race

To: Competitor's Representative: HTP MOTORSPORT

Car No.: 85 Driver's Name: EDWARD SANDSTROM

Decision of the Stewards, having received a report from the Race Director:

- Fine _____ Euros
- Drive-through penalty* converted to time penalty _____ seconds
- Stop-go penalty* _____ seconds converted to time penalty _____ seconds
- Cancellation of : lap time of infringement fastest lap time in session
- Cancellation of all lap times in session up to _____ hrs
- Time penalty of _____ seconds
- Black flag
- _____ Behaviour Warning Point(s) (Art 52 BGTS Sporting Regulations 2017)
- Other.....

Reason:

- Crossing the white line at pit lane: entry exit
- Exceeding the speed limit in the pit lane: speed _____ km /h
- Not respecting yellow flag repeatedly
- Fastest time set under yellow flag at _____ hrs at post _____
- Not respecting track limits repeatedly
- False start
- Driving through a red light at the end of the pit lane
- Causing a collision
- Forcing a driver off the track
- Illegitimately impeding another driver during overtaking
- Other DRIVE-THROUGH (DECISION 36) CARRIED OUT AFTER THE SAFETY CAR DEPLOYED.

Article: 53 b. BGTS Sporting Regulations 2017
2017 FIA International Sporting Code

*The competitor was granted a hearing before the decision. *Denotes penalties not susceptible to appeal.*

Date: 14/7/17 Time: 16:01 hrs


Greg MASTERS
Chairman of the Stewards



Etienne MASSILLON
International Steward


Richard NORBURY
ASN Steward

Received by the competitor:

Signature..... Date..... Time.....

Copy to: The Competitor; The Clerk of the Course; The Secretary of the Meeting; The Press Delegate; The Timekeepers; The Official Notice Board



Blancpain GT Series Endurance Cup

Pit Stops Race




Provisional

Silverstone, Length: 5901m
Air temperature: 20.27°C
Track temperature: 21.79°C
Weather condition: Dry

Sunday, May 14, 2017 14:55:00

Nr	Driver in	Day time in	Time in	Driver out	Day time out	Time out	Reasor	Nett Time
85	Fabian Schiller	15:46:51.831	53:07.831	Edward Sandström	15:48:24.402	54:40.402		1:32.571
85	Edward Sandström	15:52:31.858	58:47.858	Edward Sandström	15:53:12.604	59:28.604	Penalty	40.746
85	Edward Sandström	15:56:14.290	1:02:30.290	Edward Sandström	15:57:06.637	1:03:22.637		52.347



Blancpain GT Series Endurance Cup

Message List Race

Provisional




Silverstone, Length: 5801m
Air temperature: 20.25°C
Track temperature: 21.79°C
Weather condition: Dry

Sunday, May 14, 2017 14:55:00

TIME	RACE TIME	MESSAGE
15:41:33.742	47:49.742	Yellow flag at turn 4
15:42:32.670	48:48.670	CAR 44 HIT THE BARRIERS AT T3
15:42:53.033	49:09.033	Full course yellow flag
15:46:20.896	52:36.896	Green flag
15:46:22.928	52:38.928	Safety car
15:52:53.722	59:09.722	INCIDENT IN T3 BETWEEN CAR NO.31 AND CAR NO. 44 WILL INVESTIGATED AFTER THE RACE
15:58:40.599	1:04:56.599	SAFETY CAR IN AT THE END OF THIS LAP
15:59:19.075	1:05:35.075	Green flag
16:00:23.410	1:06:39.410	1 MN STOP AND GO PENALTY FOR CAR 32 CAUSING A COLLISION





Blancpain GT Series Endurance Cup

Message List Race

Provisional



Silverstone, Length: 5901m
Air temperature: 20.25°C
Track temperature: 21.79°C
Weather condition: Dry

Sunday, May 14, 2017 14:55:00

TIME	RACE TIME	MESSAGE
14:15:02.273		PIT EXIT IS OPEN
14:28:02.057		PIT EXIT CLOSES IN 2 MINUTES
14:29:59.975		PIT EXIT IS CLOSED
14:39:58.356		10 MINUTES TO START OF FORMATION LAP
14:45:03.913		5 MINUTES TO START OF FORMATION LAP
14:47:13.602		3 MINUTES TO START OF FORMATION LAP
14:49:07.444		1 MINUTE TO START OF FORMATION LAP
14:50:05.635		FORMATION LAP
14:53:44.000		Green flag
14:53:59.632	15.632	EXTRA FORMATION LAP
14:55:38.839	1:54.839	REMINDER > CARS MUST DRIVE OVER THE WHITE PIT BOXES
14:58:35.903	4:51.903	DRIVE-THROUGH PENALTY FOR CAR 16
14:58:37.567	4:53.567	DRIVE-THROUGH PENALTY FOR CAR 36
15:00:20.345	6:36.345	DRIVE-THROUGH PENALTY FOR CAR 89
15:00:22.393	6:38.393	STOP AND GO PENALTY FOR CAR 53
15:01:15.526	7:31.526	CAR 7 AND 26 MUST RESPECT TRACK LIMITS AT T1
15:03:09.947	9:25.947	DRIVER CAR 78 IS MACHITSKI
15:10:08.001	16:24.001	START UNDER INVESTIGATION CAUSED A EXTRA FORMATION LAP
15:10:55.975	17:11.975	REMAIND ALL DRIVERS TO RESPECT TRACK LIMITS IN T1
15:11:20.586	17:36.586	Yellow flag at sector 2
15:11:20.587	17:36.587	Yellow flag at turn 7
15:11:46.417	18:02.417	INCIDENT BETWEEN CAR NO. 2 AND CAR NO.11 UNDER INVESTIGATION T7
15:12:43.655	18:59.655	INCIDENT BETWEEN CAR NO. 89 AND CAR NO. 777 UNDER INVESTIGATION
15:15:54.341	22:10.341	CAR 11 REJOINED
15:16:19.784	22:35.784	SLOW CAR ON TRACK FROM T7
15:17:07.592	23:23.592	Green flag at turn 7
15:17:08.664	23:24.664	Green flag at sector 2
15:17:18.040	23:34.040	Yellow flag at sector 3
15:17:18.041	23:34.041	Yellow flag at turn 17
15:18:08.436	24:24.436	CAR 188 SPUN AT T17
15:18:24.214	24:40.214	INCIDENT CAR NO.188 IN T17 UNDER INVESTIGATION
15:19:01.269	25:17.269	Full course yellow flag
15:20:58.325	27:14.325	Green flag
15:21:01.078	27:17.078	Safety car
15:22:06.022	28:22.022	INCIDENT IN T3 BETWEEN CAR NO.77 AND CAR NO. 90 UNDER INVESTIGATION
15:23:45.539	30:01.539	SAFETY CAR IN AT THE END OF THIS LAP
15:24:07.513	30:23.513	Green flag
15:26:53.509	33:09.509	5MN STOP AND GO PENALTY FOR CAR 2 CAUSING A COLLISION
15:27:27.068	33:43.068	TEAM MANAGER OF CAR 31 TO THE RACE DIRECTOR IMMEDIATELY
15:30:00.977	36:16.977	CAR 75 MUST RESPECT TRACK LIMITS AT T6
15:35:35.080	41:51.080	1 MN STOP AND GO PENALTY FOR CAR 88 DUE TO FALSE START AND CONTACT DURING FORMATION LAP
15:40:32.349	46:48.349	DRIVE-THROUGH PENALTY FOR CAR 55 AND 85 JUMP START
15:41:33.741	47:49.741	Yellow flag at sector 1

