





BLANCPAIN GT SERIES

SPORTING NOTE #3 - 04/05/18

CLARIFICATION ON PIT LANE, SEAT BELTS AND THE DRIVER-FACING SAFETY CAMERA

VALID: 2018 SEASON -SPRINT CUP

In order to clarify articles 66 and 120 of the 2018 Sporting Regulations, the following information is given.

The onboard safety cameras were introduced in the Blancpain GT Series Sprint Cup in order to allow the officials to control the proper application of article 120, which states that: "A driver coming into the pits cannot unfasten his safety harness or racing net until his car is completely stopped in front of the pit garage. After a pit stop, the car can only start moving after the driver's safety harness and racing net have been fastened. It is the car controller's responsibility to ensure that a driver is properly buckled in before the car leaves its working area to enter the track."

Article 120 is therefore clarified as follows:

While driving in the fast lane of the pits, the driver must have at least one hand on the steering wheel at all times. He may unplug the radio or disconnect the drinks bottle and other such items but should not be distracted from watching the road ahead while doing any of these things. Tension in the belts may be loosened but the belts must remain in contact with the driver so that they are considered to still be properly restrained in accordance with ISC appendix L chapter III article 4.

The driver's safety harness must be securely fastened before the car leaves the team's working area but, on exiting the pits, the driver may further tighten the belts or adjust them.

Teams and drivers are further reminded that in accordance with article 61, the transponder must be used correctly. To ensure that the proper driver is shown at all times, the driver ID must not be changed before the car is stationary and must be correctly changed before the car crosses the pit exit loop. If an incorrect driver ID is recorded at pit entry or pit exit, a penalty may be imposed by the Stewards.

It is also clarified that in terms of articles 144 – 146, cars must move from their working area to the fast lane prior to exiting the pit lane across the pit lane exit loop.

Signed by the Sporting Board

Greg Masters

Chairman of the Stewards

Alain Adam

Race Director

Xavier Schene

RACB

Patricia Kiefer

COO

Laurent Gaudin Series Manager

Jacquie Groom Sporting Director Claude Surmont **Technical Director**















ST BARETA

