

POSTED
at 13.00m



Stewards
Log N° 39

From	The Stewards of the Meeting	Decision No 15
To	The Team Representative Barwell Motorsport	

The Stewards have received a report from the Technical Delegate that the engine of car 78 has been changed during the course of the event. The Stewards find this is a breach of Article 152 of the Blancpain GT Series 2016 Sporting Regulations.


The decision of the Stewards in respect of this breach is that all qualification times are annulled; car 78 must start from the back of the grid and is given a Stop & Go penalty of 120 seconds.

The Stop & Go penalty must adhere to the following conditions:

- To be performed after 15 minutes but before 30 minutes after the race start
- The car must not enter the pit-lane to perform its Stop & Go penalty during a FCY or Safety Car period
- If a FCY or Safety Car is in force at 30 minutes after race start, the Stop & Go penalty must be performed on the lap immediately following the withdrawal of the FCY or Safety Car

1735
BLANCPAIN
GT SERIES


Marc JANSSEN
International Steward (Chairman)


Greg Masters
International Steward
MSA (UK) Lic: 1409

Greg MASTERS
International Steward


Chris GEFFROY
ASN Steward

Date 25 June 2016

Time 12.05hrs

Received by the Competitor -

(Signature) 

Time 12.17 Date 25/06/16

Copy to:	The Competitor
	The Clerk of the Course
	The Secretary of the Meeting
	The Press Delegate
	The Timekeepers
	The Official Notice Board

REQUEST FORM
FORMULAIRE DE DEMANDE

Date: 24/06/2016

Event: Blancpain GT Series Endurance Cup - Paul Ricard

Team: Barwell Motorsport

Numéro de voiture - Start number: #78

Nom - Name: Matt Bell

Concerne - concerns:

Briefing

Free practice / essais libres

Qualifying / essais qualificatifs

Race / Course

Demande - request:

Car #78 Lamborghini Huracan has experienced an engine failure during pre-qualifying

We now must fit a brand new engine directly from the Lamborghini support truck, to allow our customers to continue with this prestigious event.

We inform you that we've broken the seal for the engine, and if we are allowed to continue, we request an inspection and a new seal.

Time - Heure: 18:50

Signature: Matt Bell

Race director's comments:

Sent to the stewards at:

This report can only be used for requests involving your team cars

Ce rapport ne peut être utilisé que pour une demande impliquant une voiture de votre team