



From

The Stewards of the Meeting

Decision N° 24

To

The Competitor's Representative

Boutsen Ginion Racing-car nr 12

The Stewards, having received a report from the Sporting Director, take the following decision.

Car/Driver

12

Competitor

Boutsen Ginion Racing

Facts

The car lost a go pro camera in turn 6, the camera was placed on the car without

permission of the technical delegate. The camera loss caused a red flag that was out at

14.30.41

Decision

Fine of 2.000 euros and the camera will be given back at the end of the 24 Hours of

Spa.

was granted a hearing before the decision. He is reminded of his/fight of appeal. The competitor

Yves BACQUELAINE International Steward

Chairman

Fred MASTERS nternational Steward Marc JANSSEN

International Steward

Richard NORBURY International Steward

Permanent Chairman BGTS

Alessandro/T/BILETTI nternational Steward

Mathieu REMMERIE **ASN Steward**

28 July 2016 Date

Time 15.45

Stewards Log Nº . 52

Received by the Competitor -

(Signature).....

Copy to: The Competitor

The Clerk of the Course

The Secretary of the Meeting

The Press Delegate The Timekeepers

The Official Notice Board







Report n° 2 from the Race Director to the stewards of the meeting

Car N° / Driver: 12

Competitor: BOUTSEN GINION (BEL)

Session: Free practice

Stewards Log N°..52

Fact: Track Incident -

Offence: Caused a practice stoppage deliberately-Art 48/162

of the Blancpain GT Series sporting regulations.

The car lost a go pro camera in turn 6, the camera was placed on the car without permission of the technical delegate. This is totally forbidden. The camera loss caused a red flag that was out at 14.30.41

Time of the offence: .14.30.40

Other driver(s) involved:

Alain ADAM
Race Director

Sent to the stewards on Thursday, 28 July 16 at 15:21

Marshal report:

Video evidence: YES







































