

From: The Technical Delegate Report N° 04
To : The Stewards of the Meeting

After the Qualifying we have checked the following elements on all cars

#4 , #72, # 63, #15, #159, #32, # 9

- Restrictor seals
- Aero
- Data
- Boost on Turbo cars
- Engine settings in general

There is nothing to report for those cars

For the car #51 impossible for the Memotech engineer to collect the data, both SD card and internal memory were empty. Logger was powered at verification after the session.

Series Technical Delegate


RACB Sport
Alain MARQUET
Commissaire Technique
Lic. 2265
