



POWERED AWS

From

The Stewards of the Meeting

To:

The Competitor - GetSpeed

All Officials

Decision N° 16

Date:

22 April 2023

Time: 11:36

The Stewards have received a report that car #777 was not earthed during refuelling:

Driver and car No: #777 Competitor: GetSpeed Time (fact): 09.25hrs Session: Free Practice

Fact: Car #777 refuelled without earthing lead connected

Offence: Breach of Article 37.1 1) of Fanatec World Challenge Europe 2023 Sporting Regulations

Decision: Fine of €500

Reason: The Stewards summoned and heard from the Representative of the Competitor.

The Stewards were given a report from the Race Director stating that Car #777 was refuelled without an earthing lead connected. The Stewards are satisfied that a breach of Article 37.1.1) occurred and impose the penalty cited above.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting, within the applicable time limits.

Greg MASTERS
Steward (Chairman)

Yves BACQUELAINE International Steward Francesco MAFFEZZONI

ASN Steward

Copy to: The Competitor

The Clerk of the Course

The Secretary of the Meeting

The Press Delegate The Timekeepers

The Official Notice Board











